DENR/DEH

ON-SITE WASTEWATER SECTION

& Repair

Sheet 1 of 1
PROPERTY ID #: 3283-88-2015
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kelly Sharpe
ADDRESS: 185 westmont Trail
PROPOSED FACILITY: 3br 1ba 1
PROPOSED DESIGN FLOW (.1949): 360 gpd
LOCATION OF SITE: Sharon School Rd. Turn onto Westmont Trail
APPLICATION DATE 9-3-2010
DATE EVALUATED: 9-
PROPERTY SIZE: 6.
PROPERTY RECORDED:
WATER SUPPLY: • Private • (Public) • (Well) • Spring • Other
EVALUATION METHOD: • (Auger Boring) • Pit • Cut
TYPE OF WASTEWATER: • (Sewage) • Industrial Process • Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 10%	0-34	sbk / cl	Fr / sap	1 48	1 48	NA	NA	PS 0.3
		34-48+	sbk / c	Fr / sap					
2	L 10%	0-29	sbk / cl	Fr / sap	1 48	1 48	NA	NA	PS 0.3
		29-38	sbk / c	Fr / sap					
		38-48+	sbk / cl	Fr / sap					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		PS
System Type(s)		~~I~~ II
Site LTAR		0.3

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: TSH
OTHER(S) PRESENT: Kelly Sharpe

COMMENTS: