DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: 3784295074
COUNTY: Iredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Clayton Homes APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7/15/15
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 1340 Sharon School Rd PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	L 5%	0-3	Brw SCL	GR SS, SP, SE FR					PS .3 to 48"
		3-48	R C/CL m-w SBK	SS, SP, SE FR		48"			
2	L 5-6%	0-5"	Brn to Rd/Brw SCL	GR, SS, SP, SE FR					PS .3 to 46"
		5-46"	R C/CL	m-w SBK SS, SP, SE FR					
			w/ Common Mica flakes						
		46-48	R C/CL w/ W. Rock Inclus	m-w SBK SS, SP, SE FR					
3	L 5%	0-5"	Brn to Rd/Brw SCL	GR, SS, SP, SE FR					PS .3 to 45"
		5-45	R C/CL	m-w SBK SS, SP, SE FR					
		45-48	R CL w/	SBK SS, SP, SE FR					
			with few	Yel/Brw W. Rock Inclus					
4	L 6%	0-9	Brn to Rd/Brw SCL	GR, SS, SP, SE FR					PS .3
		9-42	R C/CL	m-w SBK SS, SP, SE FR		48"			
		42-48	R CL	w SBK SS, SP, SE FR					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III	III
Site LTAR	.3	.3

OTHER FACTORS (.1946): None
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Maria Dotson
OTHER(S) PRESENT: _____

50
50
175
287
1340
287
114
126
SHARON SCHOOL
1 inch = 50 feet
176