10684.

35790

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

DATE 1-16-90 PERMIT NO. 8P-A-128

OWNER OR CONTRACTOR GEORGE NELSON

PHONE: Business _____ Home _____

LOCATION New Sterling Rd. off Clements Rd. - T.R. on Lindsey Loop - T.R. on Beltree Rd. go 2/10 of a mile to dirt drive - go 1/4 mile S.R. No. _____

SUBDIVISION NAME _____ LOT NO. 12-8 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 5 acres

Character & Porosity of Soil Loam & Sandy Loam

Percolation Rate 1-60 min. per inch

Topography Level to 10+

Depth to Water Table none observed

Rock or other impervious formations none observed

_____ Basement with Plumbing ✓ Basement without Plumbing _____ No Basement

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 2 Lineal Ft. 240

Sq. Ft. 120

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Tommy Gibson

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

Plot of System

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Brown DATE 1-16-90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold