DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Annette Campbell APPLICANT: Fleetwood Homes
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8/24
PROPOSED FACILITY: 3BR MH/Conv PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: .52 Ac
LOCATION OF SITE: _____ PROPERTY RECORDED: Yes
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFIL. CLASS & LTAR
1	Ridge <2%	0-8	e/sl	fr NS NP NES					PS .35
		8-38	scl	fr/fi ss sp SES					
		38-48	scl w/sap mica wet	fr ss sp SES					
2	Ridge <2%	0-6	e/sl	fr NS NP NES					PS .35
		6-35	scl some mica wet	fr/fi ss sp SES					
		35-48	scl w/sap wet	fr ss sp SES					
3	Linear 4%	0-6	e/sl	fr NS NP NES					PS .35
		6-20	scl	fi ss sp SES					
		20-34	scl w/sap	fi ss sp SES					
		34-48	sap	NES					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	Conv/Conv	Conv/Pump 250 Kit
Site LTAR	.35	.35

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Bill Johnson
OTHER(S) PRESENT: _____