9657

# IREDELL COUNTY HEALTH DEPARTMENT

## (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Bruce Hammon DATE 5-16-89 PERMIT NO. D9

PHONE: Business _____ Home _____

LOCATION Hwy 115 N. past Buffalo Creek Rd. 2 Mi. - Turn on New Sterling Rd. - T.R. on Linda Loop - T.R. on Cul-de-Sac 1st. house on R.

SUBDIVISION NAME _____ LOT NO. 1 S. R. No. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓) Character & Porosity of Soil Deep Suitable.


Auto. Dishwasher Yes ( ) No (✓) Percolation Rate Fair

Auto. Wash. Machine Yes (✓) No ( ) Topography Rolling

Site Suitable Yes (✓) No ( ) Depth to Water Table 10+

Lot Area 2 acres + Rock or other Impervious formations None Encountered.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field: No. of Lines 3

Sq. Ft. 720 Linear Ft. 240

Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Andy Davis

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

Plot of System

IMPROVEMENTS PERMIT BY Steve Baum

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Steve Baum DATE 6-16-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold