SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Clyde Hall OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: Lindsey Fm acres Lot 25
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring ✓ Pit Cu

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZ LTA
1	Linear 5%	0to48	C SbK	SEAP Fi SS SP	PS	PS	PS	N/A	.3
2	Linear 5%	0to48	C SbK	SEAP Fi SS SP	PS	PS	PS	N/A	.3
3									
4									
5									

AVAILABLE SPACE (.1945): Yes SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: J.C. Moore OTHER(S) PRESENT:
COMMENTS:

U0163