DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

*Sheet* ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: David McNeely
ADDRESS: _____
PROPOSED FACILITY: 3Br Home
PROPOSED DESIGN FLOW (.1949): 360 gpd
LOCATION OF SITE: _____
APPLICATION DATE _____
DATE EVALUATED: 30 Apr 08
PROPERTY SIZE: 5.0 ac.
PROPERTY RECORDED: _____

WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | L 15% | 0-6 | vfsk/cl | vfr/sap | 7.4Y | 74R | - | — | PS 0.3 |
| | | 6-48+ | ssk/c | fr/sap | | | | | |
| 2 | L 35% | 0-8 | vfsk/cl | vfr/sap | 7.5R | 7.5R | — | — | PS 0.3 |
| | | 8-48+ | ssk/c | fr/sap | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | PS | PS |
| System Type(s) | TE 25% Red | TE 25% Red |
| Site LTAR | 0.3 | 0.3 |

OTHER FACTORS (.1946): PS
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: TCH
OTHER(S) PRESENT: _____

COMMENTS: _____