SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Clyde Hall OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: Lindsey FM acres Lot 21
WATER SUPPLY: On-Site Well / Comm. Well Public Other EVAL. METHOD: Auger Boring / Pit Cu

PROFILE #	1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	1941 ST. STRUCTURE/TEXTURE	1941 MINERALOGY/ CONSISTENCE	1942 WETNESS COND.	1944 RESTRICT HORIZONS	1948 CLASS OF HORIZ	1937/ 1956 SAPRLT CLASS.	HORIZ LTA
1	Linear 5%	0 to 48	C SbK	SEAP Fi SS SP	PS	PS	PS	N/A	.3
2	Linear 5%	0 to 48	C SbK	SEAP Fi SS SP	PS	PS	PS	N/A	.3
3									
4									
5									

AVAILABLE SPACE (1949): Yes SITE CLASSIFICATION (1949): PS SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: J.C. Moore & THESE(S) PRESENT:
COMMENTS:

000853