34875

10289.

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR PAUL BELANGER DATE 8-10-89 PERMIT NO. 89-A-49

PHONE: Business _____ Home _____

LOCATION Old #115 Rd. north of Bradford Rd. - T.R. on Liberty Farm Rd. ½ mi. on left - Enter dirt drive - 4th lot on left. S. R. No. _____

SUBDIVISION NAME WEST IREDELL ACRES LOT NO. 4 SECTION OR BLOCK NO. _____

House ( ) Mobile Home (DOUBLEWIDE) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area 125' x 200'

Character & Porosity of Soil Gravel Suitable.


Percolation Rate Good / 5 min. per in.

Topography 2-6% slope

Depth to Water Table 10'+

Rock or other impervious formations none observed.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 900 Linear Ft. 300

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Chaffin Farms

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Steve Brown

COMMENTS: Do not drive over S.T. system.

CERTIFICATE OF COMPLETION BY Steve Brown DATE 8-10-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold