DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY I.D.#:
PROPERTY RECORDED:
COUNTY:

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Clyde Hall Enter OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: Lot #12 Lindsey Farm Acres
WATER SUPPLY: On-Site Well Comm. Well Public Other EVAL. METHOD: Auger Boring Pit / Cut

PROFILE #	.1940 LANDSCP POS./ SLOPE %	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY		
1	LINEAR	0-24	C	SBK	S-EAP	.1942 WETNES CONDITION	PS
		24-48	HEAVY CL	SBK	S-EAP	.1943/.1956 SAPROLITE	PS
						.1944 RESTRICTIVE HORIZON	PS
						.1948 PROFILE CLASSIFICATION	PS
						PROFILE LTAR	.3
2	LINEAR	0-18	C	SBK	S-EAP	.1942 WETNES CONDITION	PS
		18-30	HEAVY CL	SBK	S-EAP	.1943/.1956 SAPROLITE	PS
		30-48	CL	WEAK SBK	N-EAP	.1944 RESTRICTIVE HORIZON	PS
						.1948 PROFILE CLASSIFICATION	PS
						PROFILE LTAR	.3
3						.1942 WETNESS CONDITION	
						.1943/.1956 SAPROLITE	
						.1944 RESTRICTIVE HORIZON	
						.1948 PROFILE CLASSIFICATION	
						PROFILE LTAR	
4						.1942 WETNESS CONDITION	
						.1943/.1956 SAPROLITE	
						.1944 RESTRICTIVE HORIZON	
						.1948 PROFILE CLASSIFICATION	
						PROFILE LTAR	
5						.1942 WETNESS CONDITION	
						.1943/.1956 SAPROLITE	
						.1944 RESTRICTIVE HORIZON	
						.1948 PROFILE CLASSIFICATION	
						PROFILE LTAR	

AVAILABLE SPACE (.1945): SITE CLASSIFICATION (.1948): SITE LONG-TERM ACCEPTANCE RATE: .3
OTHER FACTORS(.1946): SYSTEM TYPE
EVALUATED BY: OTHER(S) PRESENT:
COMMENTS:

DRAFT

00512