DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY I.D.#:
PROPERTY RECORDED:
COUNTY:

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Clyde Hall Enter. OWNER: AGENT: PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED:
PROPOSED FACILITY:
PROPERTY SIZE:
LOCATION OF SITE: LOT 14 LINDSEY FARM ACRES
WATER SUPPLY: On-Site Well Comm. Well Public Other EVAL. METHOD: Auger Boring Pit / Cut

PROFILE #	.1940 LANDSCP POS./ SLOPE %	HORIZON DEPTH (IN.)	.1941 (a)(1) TEXTURE	.1941 (a)(2) STRUCTURE	.1941 (a)(3) MINEROLOGY	
1	linear 2%	0 to 24	C	ABK	S-EAP	.1942 WETNES CONDITION - ~~PS~~ PS
		24 to 48	CL	SBK	S-EAP	.1943/.1956 SAPROLITE - PS
						.1944 RESTRICTIVE HORIZON - PS
						.1948 PROFILE CLASSIFICATION - PS
						PROFILE LTAR - .3
2	Linear 2%	0 to 48	C	ABK	S-EAP	.1942 WETNES CONDITION - PS
						.1943/.1956 SAPROLITE - PS
						.1944 RESTRICTIVE HORIZON - PS
						.1948 PROFILE CLASSIFICATION - PS
						PROFILE LTAR - .3
3						.1942 WETNESS CONDITION -
						.1943/.1956 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
4						.1942 WETNESS CONDITION -
						.1943/.1956 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -
5						.1942 WETNESS CONDITION -
						.1943/.1956 SAPROLITE -
						.1944 RESTRICTIVE HORIZON -
						.1948 PROFILE CLASSIFICATION -
						PROFILE LTAR -

AVAILABLE SPACE (.1945) SITE CLASSIFICATION (.1948): SITE LONG-TERM ACCEPTANCE RATE: .3
OTHER FACTORS(.1946) SYSTEM TYPE
EVALUATED BY: OTHER(S) PRESENT:
COMMENTS:

DRAFT