## IREDELL COUNTY HEALTH DEPARTMENT

### (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Jerry Hayes DATE 2 Nov 73 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION Hwy 90 to Stony Point - Turn left behind Stony Point Furniture 1st street on left. (Double-wide) S. R. No. _____


SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2

| | | | | |
|---|---|---|---|---|
| Garbage Disposal Unit | Yes (✓) | No ( ) | Character & Porosity of Soil | Yellow brownish clay - some gravy |
| Auto. Dishwasher | Yes (✓) | No ( ) | Percolation Rate | fair |
| Auto. Wash. Machine | Yes (✓) | No ( ) | Topography | slight slope |
| Site Suitable | Yes (✓) | No ( ) | Depth to Water Table | very close - 2-3 ft. |
| | | | Rock or other impervious formations | none given rock |

Lot Area _____



Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 637½ Linear Ft. 255
Depth of Stone in Lines 10"
Water Supply: Individual ( )
Public (✓)

Installed by Lakey Brothers

IMPROVEMENTS PERMIT BY _____

COMMENTS: Septic Tank installed in very marginal soil. Low area with 2-3 ft of water table. Must be well drained and maintained properly.

CERTIFICATE OF COMPLETION BY William M. Howard DATE 2 Nov 73

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold