DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Kenneth Beeler Homes
ADDRESS: _____
APPLICATION DATE _____
DATE EVALUATED: 9-19-05
PROPOSED FACILITY: Residential PROPOSED DESIGN FLOW (.1949): _____
PROPERTY SIZE: .669 AC
LOCATION OF SITE: Brawley Sch. Rd. TR Tuscarora Tr. TR Tusc. Pt. Lot 15
PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	8%	0-6	1sbk l			48			PS .3
		6-36	1sbk/1abk cl	fr ss/sp se					
		36-48	1sbk/1abk cl+sap						
2		0-8	1sbk cl			48			PS .3
		8-35	1sbk/1abk cl	fr ss/sp se					
		35-48	1sbk cl+sap						
3		0-6	1sbk cl			48			PS .3
		6-32	1sbk/1abk c	fr ss/sp se					
		32-48	1sbk c+sap						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	yes
System Type(s)	25% red	LP panel
Site LTAR	.3	.3

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Judy Melville
OTHER(S) PRESENT: _____

COMMENTS: _____