DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Greg Garczyinski Kenneth Bealer Homes
ADDRESS: ___
APPLICATION DATE ___
DATE EVALUATED: 9-19-05
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): 480
PROPERTY SIZE: ___
LOCATION OF SITE: Brawley sch Rd TR Tuscarora Tr. at corner on Pr Lot 2
PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	10 % sideslope	0-8	1 sbk 1			48			PS .3
		8-48	1 sbk/2 mk cl	fr ss/sp se					
2	sideslope 15" of pit auger to 48"	0-9	1 sbk 1	fr		48			PS .3
		9-23	2 abk/2 sbk c	ss/sp se					
		23-38	C f sap						
		38-48	1 sbk c	ss/sp se					
3		0-7	1 sbk 1	fr		48			PS .3
		7-48	1 sbk/2 sbk c	ss/sp se					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	yes
System Type(s)	LP panel	LP panel
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Judy Melville
OTHER(S) PRESENT: ___

COMMENTS: soil conditions very dry when sampled