COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Paul V. Kelly — DATE REQUESTED: 8-7-80

ADDRESS: Judell — PLAT NO.: LN Ke 6 Lot 143

COUNTY: Judell — LOT SIZE: .71 Acre

LOCATION OF SITE: 100 TR 1236 Bear left at stop sign BR on 1236 about .5 mile on left after curve

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U — 2-8%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) U clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) U clayey Sub Angular	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS U 48"	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	(S) PS U none observed	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) PS U No mottles	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) U Slope	S PS U	S PS U	S PS U
8. OTHER (Specify)	S (PS) U RS	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	PS			
SOIL SERIES	Lloyd			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: Follow contours - keep system 15' from small draw — 5' off property lines

Described By: MC

Title: S-T — Date: 8-7-80

DHS Form 2601 (2/77)
Sanitation