IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Harry De Jong DATE Jan. 15, '79 PERMIT NO. 17

PHONE: Business _____ Home _____

LOCATION 1100 T.R. on 1177 T.L. on 1458 ~ 3/4 mi. on Rt.

_____ S. R. No. _____


SUBDIVISION NAME _____ LOT NO. 92 SECTION OR BLOCK NO. 7

House (✓) Mobile Home ( ) Business ( ) Other 1 Bedroom, 1 Bathroom addition (with addition)

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	
			Rock or other impervious formations	

Lot Area _____



Plot of System

Size of Tank existing Gals.
Nitrification Field:
No. of Lines existing
Sq. Ft. _____ Linear Ft. _____
Depth of Stone in Lines _____
Water Supply: Individual ( )
Public ( )

Installed by _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: No surfacing of sewage was found during inspection of existing system.

CERTIFICATE OF COMPLETION BY David R. Hinson DATE Jan. 15, '79

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold