Department of Natural Resources and Community Development
Division of Environmental Management

P. O. Box 27687 - Raleigh, N. C. 27611

WELL ABANDONMENT RECORD

CONTRACTOR ABT Construction REG. NO. 14543

1. WELL LOCATION: (Show a sketch of the location on back of form.)
   Nearest Town: Mooresville County Iredell
   Lakeview "Lot" 234 Quadrangle No.
   (Road, Community, Subdivision, Lot No.)
2. OWNER: Craig Schmidt
3. ADDRESS: Hopedale Ave Charlotte
4. TOPOGRAPHY: draw, slope, hilltop, valley, flat
5. USE OF WELL: Residential DATE: Nov 86
6. TOTAL DEPTH: 47' DIAMETER: 2"
7. CASING REMOVED:

feet	diameter
6	2"

8. SEALING MATERIAL:

Neat cement	Sand cement
bags of cement	bags of cement .75
gals. of water	~~yds.~~ ft³ of sand .75
	gals. of water 25


Other
Type material
Amount

9. EXPLAIN METHOD OF EMPLACEMENT OF MATERIAL.
Loose grout was mixed w/clean bucket poured slowly - tamped into well to ≈5' from top - Casing was removed & well was filled & capped on top

I do hereby certify that this well abandonment record is true and exact.

Orlin C. Kerr 5/7/87
Signature of Contractor or Agent Date


WELL DIAGRAM: Draw a detailed sketch of the well showing total depth, depth and diameter of screens remaining in the well, gravel interval, intervals of casing perforations, and depths and types of fill materials used.



10. Chlorination	% Chlorine	Amount Used
	70%	1 tablespoon

11. Remarks

Submit original to the Division of Environmental Management, one copy to the Driller, and one copy to the Owner.



Lakeview Subdivision
Lot # 234