Division of Environmental Health
On-site Wastewater Section

Property ID: 4624-05-4126
Lot #: Sec 6 Lot 376
File #: 159060
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: John & Judy Maples
Applicant: Beau Paxton
Address: 3565 Tralee Ct Naperville, IL
Date Evaluated: 12/12/2009
Proposed Facility: Addition
Design Flow (.1949) 480 GPD
Property Size: .64 AC
Location of Site: 129 Bearcreek
Property Recorded: Yes
Water Supply: [ ] Public [x] Individual [x] Well [ ] Spring [ ] Other
Evaluation Method: [x] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: [x] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
#1	4%	0-16	SCL,W,SBK	SS,SP,SEXP,VFR	NA				
	LINEAR	16-30	SC,M,SBK	SS,SP,SEXP,VFR	NA				
		30-47	CL,M,SBK	SS,SP,SEXP,VFR	NA				
		47+	LSAP,MASS	NS,NP,VFR	NA	47"	S	NA	.3

Description	Initial System	Repair System
Available Space (.1945)	PS	PS
System Type(s)	PM PANEL	LP PANEL
Site LTAR	.3	.3

Other Factors (.1946): NA
Soil Evaluation By: Ben Aldridge
Others Present: None
ite Classification (.1948): PS
Site Evaluation By: Ben Aldridge
Others Present: None

Sheet:
FILE #:

COMMENTS: Earlier soil work done by Brady Freemon (formorly of ICHD)