ON-SITE WASTEWATER SECTION

OWNER: Mark Austin APPLICANT:

ADDRESS: DATE EVALUATED: 1/23/04

PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:

LOCATION OF SITE: 116 Balmoral PROPERTY RECORDED:

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other

EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-18"	Brn SCL	w SBK					PS .3
		18"-30"	R to RBrn C	m SBK	SS, SP, SE, Fi to FR				
		30-48"	Rd CL	w SBK	SS, SP, SE FR w/ Few				
			Yel/Brn	mottles	at 36"				
2 Repair In Front		0-4	Brn SCL						PS .25 to .3
		4-24	R C	m SBK	SS, SP, SE, FI FR				
		24-48	Rd/Brn C/C	m-w SBK	SS, SP, SE, FR				
			w/ Few to many		Yellow/Brn mottles				
			starting at		30"				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): SHS

SITE CLASSIFICATION (.1948): PS

EVALUATED BY: 20 12" Rock

OTHER(S) PRESENT: LO