4624197457

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR W.T. Barrow DATE 8-30-18 PERMIT NO. 207

PHONE: Business _____ Home _____

LOCATION 1100 TR on 1236 1 mi on right

S. R. No. _____


SUBDIVISION NAME L.D. LOT NO. 78 SECTION OR BLOCK NO. 6

House ( ) Mobile Home (✓) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	Clay loam
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	60 min/in
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2 2% Slope
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4 to 6'
			Rock or other impervious formations	None

Lot Area 1.3 acre



Plot of System

Size of Tank 2 1000 Gals.

Nitrification Field:
No. of Lines 2
Sq. Ft. 200 Linear Ft. 100
Depth of Stone in Lines 10"

Water Supply: Individual (✓)
Public ( )

Installed by S&P

IMPROVEMENTS PERMIT BY _____

COMMENTS: Need to grout Septic in Dec

CERTIFICATE OF COMPLETION BY John Houston DATE 8-30-18

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold