Site Address: 148 Ripplewater Ln - Mrsvl. 4:00 ✓

IREDELL COUNTY HEALTH DEPARTMENT

STATESVILLE 704-878-5305 MOORESVILLE 704-664-5281

IMPROVEMENT PERMIT / AUTHORIZATION TO CONSTRUCT / OPERATION PERMIT / EXISTING SYSTEM INSPECTION

PERMIT # 114956 210550 PIN # 4624229758 ✓ DATE 8-30-12

OWNER or APPLICANT Crescent Resources LLC/Diane Vaynick PHONE: Business 828 478-2130 Home: Paul 704996-6330

OWNER or APPLICANT ADDRESS P.O Box 396 Terrell, NC 28682 (Donald Reid)

LOCATION / DIRECTIONS Brawley School Rd TL Ripplewater at end on right.

SUBDIVISION CLAT BLOCK / SECTION 6 LOT # 45 LOT AREA .64Ac DESIGN FLOW 480gpd L.T.A.R. .3

Septic Tank 1000 Gallons: STB 794 Date 3-14-16

Pump Tank 1000 Gallons: PT 27 Date 3-8-16

Pump Make ____ Model ____ Serial # ____

Nitrification Field No Fields ____ No Lines 4 Linear Feet 270'

Trench Width min 2ft Max. Trench Bottom Depth 36" Gravel Depth N/A

☒ New System ☐ Repair ☐ Expansion System Type I II III IV V VI

System Description: Pump LP Panel Block

Repair System Description: Partial Repair LPPPBS

Maintenance Agreement Required ☒ YES ☐ NO

☐ GRAVITY ☒ PRESSURE

☒ Residence No. Bedrooms 4 ☐ Business No. Persons ____ ☐ Other No. Employees ____

☐ Slab ☐ Crawl Space ☐ Basement w/plumbing ☐ Basement w/o plumbing

Water Supply: ☒ Private ☐ Public ☐ Community

Comments / Conditions: Note: Per Zoning okay to do 50'X60' House box. 5/16/15 Reviewed floor plans, in Compliance with Septic plan.

Comments / Conditions: ☒ Lot deeded prior to 1983. (Repair exempt) ☒ Must hug property line with Driveway ☒ This permit replaces previous permit dated 9-2-03

INITIAL SITE SKETCH

See attached plan by SAME (Paul Penninger)

Approved by TCHD

AS BUILT SKETCH

No vehicular traffic in Septic area

> 60' Howell

30' to House

4/20/16 Checked lines & tanks.

	Date	Initials
Drain Lines Checked	4/20/16	MD
Tanks Checked	4/20/16	MD
Pressure Manifold or Valve Box Checked	6-20	BA
Pressure Head Set		BA
Electrical Checked		BA
Floats Set		BA
Alarm Checked		BA
Maintenance Contract (Y) N	7/18/16	MD

Permit can be suspended or revoked if any false information is supplied toward securing the permit / any unauthorized changes are made to th

☐ IMPROVEMENT PERMIT w / plat valid without expiration. ☐ IMPROVEMENT PERMIT w / site plan valid for 60 mos. ☐ AUTHORIZATION TO CONSTRUCT valid for period equal to IMPROVEMENT PERMIT-not to exceed 60 mo.

Owner / Applicant Signature: ____ Date 9-5-12

Improvement Permit by: Maria Dotson RS Date 8/31/12

Authorization to Construct by: Maria Dotson RS Date 5/16/15

Installed by: Bass Grading

Operation Permit by: Maria Dotson RS Date: 7/18/16

Existing System Inspected by: ____ Date: ____

YOU SHOULD CONTACT A LOCATOR SERVICE PRIOR TO ANY EXCAVATION.

WHITE COPY Environmental Health YELLOW COPY (Final) Owner / Applicant PINK COPY (Initial) Owner / Applicant

Crescent Resources, LLC
Lot 458 - Ripple with
Re-Layout

5 : 36 Sq 1580 - 05 - 008

8 - 28 = 12

1" = 50'

