DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 969 Point PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-6 | BSL/GR vfr | fr SSSP | | | | | PS .3 |
| | | 6-30 | RC GRV | fr SSSP | | | | | |
| | | 30-42 | CL MSBK | fr SSSP | -fc-SHP | | | | |
| | | 42-96 | RYR/PSL MSBK | fr SSSP | | | | | |
| | | | | | | | | | |
| 2 | | 0-25 | BSL/GSL VFR | fr SSSP | | | | | PS .3 |
| | | 25-48 | RC/CL MSBK | fr SSSP | P | | | | |
| | | 48-60 | YR CL FEW SHP/MSBK | fr SSSP | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 3 | | 0-5 | BSL VFR | fr SSSP | | | | | PS .2-.25 |
| | | 5-30 | RC SBK | fr SP/SSSP | | | | | |
| | | 30-40 | YRC ABK | fr SP-SBP/SSSP | | | | | |
| | | 40-50 | RYL MSBK | fr SSSP | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____