DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: 984 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9	BSCL GR	fr SSSP	30" 2 chroma 3				PS .1
		9-40	BC AB	fr SP					
		40-53	RCL MSAW	fr SSSP					
2	#65	0-7	BSL/SCL GR	fr SSP	few fine YB				.45 .25
		7-36	BC AMK	fr SP					
		36-54	RCL WSAW	fr SSP					
3		0-27	MC AMK	fr SP					.45 .25
		27-54	RCL MSAW	fr SSP					
4	#45	Water							(4)
			AMK/ YB						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

990
AC.
60'
86'
118'
DRIVE
27'
969
0.83 AC.
70x85
805
241'
167'
800
20' PSDE
136'
DRIVE
989
0.96 AC.
See Plat
113'
147'
136'
NO ACCESS
221'
234'
140'
205'
418'
985
1.24 AC.
984
0.90 AC.
395'
1.30 AC.
144'
197'