20' PSDE

30' BUFFER

NO ACCESS THROUGH BUFFER

985
1.24 AC.

986
1.30 AC.

987
1.11 AC.

DEDHAM LOOP

50' PUBLIC R/W

DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: _____
LOCATION OF SITE: 986 PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	*986	0-16	RL MASK	fi SP	few SAP + Quartz				PS .3
		16-44	LCR WSBK	fr SSSP					
2		0-4	BSCL GR	fr SSSP	few SAP				PS .3
		4-24	RC MBK	fr SSSP					
		24-44	RCL MSBK	fr SSSP					
		44-96	SL SAP	fr SSSP					
3		0-12	SCL GR	fr SSSP	few YB				.25
		12-25	CL MSBK	fr SSSP					
		25-54	RC MASK	fi SP					
4		0-4	BSCL GR	fr SSSP					PS .3
		4-24	RC MBK	fr/fi SP/SSSP					
		24-55	RCL MSBK	fr SSSP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____