DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICATION DATE: ___
ADDRESS: ___ DATE EVALUATED: ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: ___ PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut 958 A 1) 0-10 BSCL WR fr SSSP 10-40 YRC ABK fr SP-YR
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	958A 1)	0-6	BSCL WSAK	fr SSSP	Orange mottles -2.5Y 6/4 common	SAP			.2
		6-36	ABK YR C	fi SP					
		36+2	MANK YRCL	fri SP					
2	2) 959	0-11	RSCL f WSAK	fri SSSP					
		11-29	RC MAK	fri SP	few YR's				
		29-50	YRCL SAPRIMK	fi SSSP	few YR's	SAP			.25
3	3) 959	0-6	BSCL GR	fr SSSP					
		6-24	SAPRO	fri SP					
		24-52	C/ MPSAPRO	fr SSSP					.3
4	958A 1)	0-2	BSCL WR	fri SSSP					
		2-33	MSAPRO YRCL	fri SP					
		33-56	YRCL WSAK	fr SSSP	common	SAP			.25

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

COMMENTS: ___

3) 0-13 BSL/SCL WR fr SSSP 958A 2) 0-10 BSCL WR fr SSSP
13-42 R/MK C SAPRO fri SP-YR's 10-42 RC ABK fi SP-YR's .25
42-51 YRCL SAP fri SSSP -.25 fr SAP 42-48 YRCL MPSAPRO fr SSSP