Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet:
Property ID: 4624-35-6566
Lot #: 493
File #: REPAIR
AppID:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner:	KEVIN BISHOP			Applicant:	SAME
Address:	265 GAINSWOOD DR. MOORESVILLE, NC 28117			Date Evaluated:	9/29/2011
Proposed Facility:	SFR	Design Flow (.1949)	360	Property Size:	1
Location of Site:	SAME			Property Recorded:	YES
Water Supply:	[ ] Public	[X] Individual	[X] Well	[ ] Spring	[ ] Other
Evaluation Method:	[X] Auger Boring		[ ] Pit	[ ] Cut	
Type of Wastewater:	[X] Sewage		[ ] Industrial Process	[ ] Mixed	

PROFILE #	1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
AB 1	LINEAR 3%	0-30	FILL		NA	0"	NA	NA	U
		30+	COULD NOT	AUGER AND FURTHER					
AB 2	LINEAR 3%	0-48	FILL		NA	0"	NA	NA	U
AB 3	LINEAR 3%	0-29	C,M,SBK	SS,FR	NA	48"	NA	48+	.3
		29-48	SC,M,SBK	SS,FR					
AB 4	LINEAR 3%	0-29	C,M,SBK	SS,FR	NA	48"	NA	48+	.3
		29-48	SC,M,SBK	SS,FR					

Description	Initial System	Repair System
Available Space (.1945)		PS
System Type(s)		G-25%
Site LTAR		.3

Other Factors (.1946):

Soil Evaluation By: BEN ALDRIDGE, RUSSELL WILLIAMS

Others Present: HOMEOWNER

Site Classification (.1948): PS

Site Evaluation By: BEN ALDRIDGE, RUSSELL WILLIAMS

Others Present: HOMEOWNER