DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 12-18-02
LOCATION OF SITE: Lot 11 Blo Phase II The Pt. PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

48 "4"b

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-8	wkgsk lmsl	frssp					.2-.25
		8-29	mtpb RC	frsp	few common gbrm soft Mn				.3
		29-53	wkgsk grcl	frsssp	few mod sap				
		-79	" cl		few-common mod sap				
2	2-4%	0-6	wkgsk pbmsl	frssp					.25
		6-54	mtpb 1" SBK RC	fr.sp	few fine mottles to 24" few mod sap			Petr deepen	
3		0-10	gr-wkgsk lmsl	frsssp					.2-.25
		10-31	mtpb RC	frsp					.3
		31-55	wkgsk grcl	frsssp	slkp common mod sap				
		-72	" cl						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)	Conv 25%	Conv 25%
Site LTAR	.25	.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): S
EVALUATED BY: DH
OTHER(S) PRESENT: LO Customer

COMMENTS: Unsuit 42-48" to depth - still soil to 72" - Lots petr deepen