VISION OF ENVIRONMENTAL HEALTH
N-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: CRT
ADDRESS: _____
APPLICANT: _____
PROPOSED FACILITY: _____
APPLICATION DATE: _____
DATE EVALUATED: 12-18-02
LOCATION OF SITE: lot 114 phase II Thorpe
PROPOSED DESIGN FLOW (.1949): 480 gpd
PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☑ Public ☐ Well ☐ Spring ☐ Other _____
PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

| .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|
| 8-10% | 0-10 | gr lmsl | frssp | | | | | .25 @ c 345 .2 734 |
| | 10-34 | mSBK R C | frssp | Fe/manganese concretions | | | | |
| | 34-46 | wkSBK Rbrn cl | frssp | many manganese concretions | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | 0-12 | gr mkSBK brn scl | frssp | | | | | .3 |
| | 12-54 | mSBK R cl | frssp | many yellowish mottles & manganese | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | 0-6 | gr lmsl | frssp | | | | | .3 |
| | 6-50 | mSBK R C | frssp | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Suitable Space (.1945) | | |
| System Type(s) | LPP BBS | LPP BBS |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS Jan. 1956
EVALUATED BY: DRT