VISION OF ENVIRONMENTAL HEALTH

PROPERTY ID #:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

ADDRESS:

PROPOSED FACILITY: APPLICATION DATE: DATE EVALUATED: 8-16-01

LOCATION OF SITE: lot 548 phase 8 Th. of PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other PROPERTY RECORDED:

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
(1)	0-12	(cemented) massive brwsl	fi					.2-.25
	12-33	wk sbk RBm	c common manganese coatings				fi sp	.3
	33-51	wk sbk yr cl	fr sss p					
M-22 TCI	0-4	wk sbk brwsl	fr sss p					
	4-34	sbk brn RC	many fine manganese coatings fi sp					.25
	34-48	sbk cl	fr sss p					
(2)	0-5	cemented massive brwsl	fi					
	5-24	m-sbk RC	fi sp					.3
	24-56	m-sbk Rg-yr cl	fr sss p common sapric					
(3)	0-4	wk sbk (dense) brwsl	fi-fr sss p					
	4-18	sbk	RC fi sp sap	few fine sap				.3
	18-51	m-wk sbk yr cl	fr sss p	common fine sap				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Suitable Space (.1945)		

OTHER FACTORS (.1946):

SITE CLASSIFICATION (.1948):

EVALUATED BY: