4624 8887 46

IREDELL COUNTY HEALTH DEPARTMENT

13400

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Robert Terry DATE 10/17/91 PERMIT NO. 2C-1-13-8

PHONE: Business _____ Home 896-7043

LOCATION Wally Rd; Brawley TL on Yacht Rd., beau (R), past Yacht Cove to Lot on (R)

SUBDIVISION NAME Yacht Harbor LOT NO. 8 S. R. No. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash. Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Lot Area 20,000 Ft²

Character & Porosity of Soil P - C - SLC (Af-As)
Percolation Rate .3
Topography 2-3%
Depth to Water Table >48"
Rock or other impervious formations None found

_____ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 5 @ 80'x3'
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"

Water Supply: Individual (✓) NOT DRILLED YET
Public ( )

Installed by Rowan Septic Tank

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Wesley Sparks R.S. DATE 10/17/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

ermit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making nprovements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold