DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 1
PROPERTY I.D.#: 2C2A12
PROPERTY RECORDED: YES
COUNTY: Hoke

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Bob MacLeod
ADDRESS: _____ OWNER: _____ AGENT: _____ PHONE: _____
APPLICATION DATE: _____ DATE EVALUATED: 9/3/93
PROPOSED FACILITY: 3 bedroom SF Dwelling
PROPERTY SIZE: _____
LOCATION OF SITE: Lot 2, Hackl Cove
WATER SUPPLY: On-Site Well ✓ Comm. Well ___ Public ___ Other _____ EVAL. METHOD: Auger Boring ✓ Pit ___ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	55	0-24	sbk, c	l&l/fr	—	—	PS	—	.35
		24-42	wksbk, c	l&l/fi-fr	—	—	PS	—	.3
2									
3									
4									
5									

AVAILABLE SPACE (.1945): PS SITE CLASSIFICATION (.1948): PS per 1956 SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: DHumphrey OTHER(S) PRESENT: Bob MacLeod
COMMENTS: Repair may require PPBPS due to available space.