DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 2
PROPERTY ID #:
COUNTY:


# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: CRT
ADDRESS:
APPLICANT:
APPLICATION DATE:
DATE EVALUATED: 5/13/97
PROPOSED FACILITY:
PROPOSED DESIGN FLOW (.1949): NOW 35A
PROPERTY SIZE:
LOCATION OF SITE: 36A Hickstown Rd
PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | L 2-4% | 0-6 | gr sl | | | | | | PS .34 |
| | | 6-25 | SaCL rc | fr | | | | | |
| | | 25-48 | SaCL rcl | fr | | | | | |
| 2 | L 2-4% | 0-10 | SiCL rc | fr | | | | | PS .3 |
| | | 10-48 | MuSiCL rcl | fr | | | | | |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT:


TOTAL
RIP
29.
124.66'
100.18'
224.84'
414.84'TOTAL
C.M.
152.82'
50
95.70'
RESERVED COS
15.00
S37°14'04"W
160.77'
42
64.03'
110.18'
30.51'
36A
115.25'
54.36'
29.54'
22.68'
78.07'
2.27
90.00'
90.00'
CEDAR
BLUFF
24A
N61°32'54"W
96.50'
35.53'
N68°18'32"
241.68'
30
N68°18'32"
267.2
31