BASEMENT
CRAWL
S38°17'48"W
231.01'
S75°14'05"W
294.45'
120'SETBACK
45
DRIVE
N49°58'24"W
186.10'
63'SETBACK
25.27'
46
71.18'
23.18'
41.93'
4.57'
S29°05'42"E
228.13'
47

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT — APPLICANT: _____
ADDRESS: _____ — APPLICATION DATE: _____ — DATE EVALUATED: 7-22-96
PROPOSED FACILITY: _____ — PROPOSED DESIGN FLOW (.1949): _____ — PROPERTY SIZE: _____
LOCATION OF SITE: Lot 42 Harbour Sect 5 — PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☑ Public ☑ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1	0-8%	0-4	gr brusl						
		4-16	SAB RC	fi sp 1"					
		16-18	MSAB RCL	fr fi sp 1"					
2	L 0-8%	0-5	gr brusl	fr					
		5-16	SAB RC	fi sp 1"					
		16-42	MSAB RCL	fr fi sp 1"					
3	L 0-8%	0-4	SL						
		4-27	SAB RC	fi sp 1"					
		27-46	MSAB RCL	fr ss sp 1"					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____