DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 12E
PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CR1 APPLICANT:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 4/17/97
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): 480 gpd PROPERTY SIZE:
LOCATION OF SITE: Harbor Phase VI Lot #41 PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other Now Lot 40
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LL 3%	0-10"	SCL GR	Brw SS,SP					.3
		10"-24"	Red-Brw C mSBK	S,P,SE,mSBK,Fi					
		24"-48"	Red-Brw CL mSBK	SS,SP,SE,mSBK,	Fi-FR				
2	LL 3-4%	0-7"	SCL GR	Brw SS, SP					.3
		7"-30"	R-Brw C mSBK	S,P,SE Fi					
		30"-48"	Heavy CL mSBK	SS,SP,SE Fi-Fr					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR	.3	.3

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Maria Dotson
OTHER(S) PRESENT: