DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ___ APPLICATION DATE ___
ADDRESS: offsite septic DATE EVALUATED: 4-6-06
PROPOSED FACILITY: Residential PROPOSED DESIGN FLOW (.1949): 480gpd PROPERTY SIZE: 120' x 120' septic
LOCATION OF SITE: Bay Harbour Rd between Sanibel Ln & Island Cove PROPERTY RECORDED: Lot 10 .58Ac
Cades Cove Ln Lots 10 & 10A
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☑ Other community
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	5%	0-3	1 gr l			48			PS .3
		3-40	1sbk/1sbk c	so/ss/sps E					
		40-48	1sbk cl						
2		0-4	1 sbk scl			48			PS .3
		4-42	1sbk c	Cu ss/sp SE					
		42-48	1sbk cl						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	yes
System Type(s)	25%	pond
Site LTAR	.3	.3

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: S. Melville
OTHER(S) PRESENT: ___

COMMENTS: ___