DEH ENVIRONMENTAL HEALTH
WASTEWATER SECTION

COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

PROPOSED FACILITY: QRI
LOCATION OF SITE: Harbour PH IV Lot #49
WATER SUPPLY: ☐ Private ☒ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

APPLICANT:
APPLICATION DATE: 4/10
PROPOSED DESIGN FLOW (.1949): 440 NOW 660
DATE EVALUATED: 4/24/97 5/1/97
PROPERTY SIZE:
PROPERTY RECORDED:

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	2 15%	0-7	gr brn sl	fri	18"+				
		7-24	sbk brn cl	fri sp sbp					
		24-36+	gr-bk gl cl						
2	Pit	0-48"	Rd C — CL						PS .3
3	AH-2	0-24	Heavy CL — C	mSBK SS, SP, F, Fr					
		24-48"	SCL-CL w/	SBK Fr, SS, SP, Fr	B-C Common incl of SAP				.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)	Pressure Panel	Off-site
Site LTAR	.3	.3

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948): PS
EVALUATED BY:
OTHER(S) PRESENT: