DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet 1 of 2
PROPERTY ID #:
COUNTY:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT — APPLICANT:
ADDRESS: — APPLICATION DATE: — DATE EVALUATED: 4/3/97
PROPOSED FACILITY: — PROPOSED DESIGN FLOW (.1949): — PROPERTY SIZE:
LOCATION OF SITE: Lot 2 Harbour — PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	old pit	0-6	gr sCL	fr					RS .3
		6-33	sbk RCL	fr sl sticky					
		33-57	M sbk RCL	fr slsticky					
			few relic inclus						
2	L 16%	0-10	gr rbrnscl	fr					RS .3 @ 36"
		10-18	sbk RCL	fr sl sticky					
		18-38	sbk RCL						
			numerous fe-bearing nodules						
			hit some rock - end stopped						
3		0-25	sbk scl/c	fr sl sticky	25"+				LPP only .125
		25-30	sbk RCL	fr sl sticky					
4	L 16%	0-15	gr brn scl	fr					RS .125
		15-36	sbk brn RCL	fr sl sticky	few manganese staining/ few prominent fe				
		36-47	mass RCL	fr sl sticky	few brn motles				

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT:

HS 0-7 gr sm sCL fr
7-48 SBK RCL few fe/Mn patches