DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 5-28-96
PROPOSED FACILITY: ~~site~~ Elementary PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: ~~off~~ Harbour phase III PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR. HORIZ.	PROFILE CLASS & LTAR
1 68A	L 6-8%	0-4	A brwscl						.3+
		4-29	~~HSAB~~ RC	fi sp 1:1					
		29-46	HSAB RCL	fr ss, sp 1:1					
2 14A	L .8%	0-4	md br scl	gr fri 1:1					.3+
		4-42	red C	s m-f SAB 1:1					
		42-48	yel HWR+SAP	fri ss sp 1:1					
3 38A 26	L 16%	0-48	SAB RC/CL	fr-fi					.3+
4 .3+	L 4-6%	0-45	SAB RC/CL	fr ss sp 1:1					.3+

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

SANIBEL LN.
67
68
69
70
71
I
I
I
Drive
Basement
78.08'
39.09'
158.18'
80'
156.60'
30.94'
29.38'
59.23'
207.48'
100.05'
198.44'
184.27'
14.17'
129.26'
122.33'
182.29'
121.45'
136.07'
32.21'
159.54'
95.84'
98.7'
98.40'
87.3'
216.92'
135.62'