DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: CRJ OWNER: AGENT: PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 8/22/25
PROPOSED FACILITY: ____
PROPERTY SIZE: ____
LOCATION OF SITE: lot 35 Hardcastle
WATER SUPPLY: On-Site Well ____ Comm. Well ____ Public ____ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ____ Cut ____

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	LSS 6-8%	0-3	gr. fsl	vfr	SS,sp.				.3
		3-20	csbk nc	fr					
		20-47	mod-wk sbk ecl common fine roots	fr					
2		0-3	gr sl	fr					.3
		3-31	wk sbk nc	fr SS,sp					
		31-43	wk sbk cl common fine roots	fr SS,sp					
3									
4									
5									

AVAILABLE SPACE (.1945): ✓ SITE CLASSIFICATION (.1948): Spen 1956 SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: DHD OTHER(S) PRESENT: P. Keegan
COMMENTS: Unpublished (sampled) of L98255 Report 0

37
36
35' SETBACK
35
BASEMENT
CRAWL
107.5' SETBACK
34
COMMON OPEN
L100
L101
L99
L98
36
127' SETBACK