DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM


OWNER: CRA APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 2-10-17
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 72 Fairlawn 4 PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | R 2-4% | 0-5 | gr loam sol | fr | | | | | PS .3 |
| | | 5-24 | mod sbk RC | fr SS SP | | | | | |
| | | 24-48 | mod sbk RCL | fr SS SP | | | | | |
| | | | many fine mica ↓ | | | | | | |
| 2 | L 4-6% | 0-48 | ps. R c/cl | fr SP SP | | | | | PS .3 |
| 3 | | | | | | | | | |
| 4 | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | | |
| System Type(s) | | |
| Site LTAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____


24
OS
27 AC.
DRIVE
134.09'
23.74'
1.77'
19.26'
32.44'
53.85'
38'
B/C
50'
R/W
219.91'
109.50'
25.27'
28.70'
134' SETBACK
61' SETBACK
46.68'
30.47'
75.84'
25.63'
100.00'
313.47'
275.00'
149.37'
315.62'
162' SETBACK
368.93'
CRAWL
23
60'
BASEMENT
22
CRAWL
60'
BASEMENT
21
CRAWL
60'
BASEMENT
DRIVE
DRIVE
DRIVE
DRIVE