DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CKI
ADDRESS: _____ APPLICANT: _____
PROPOSED FACILITY: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
LOCATION OF SITE: 21A Revisit Harbour Pt PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1A	Slightly Cc 2%	0-3	6RN SCL	fr					
		3-24	MSBk RCL	fr SP sss SZP	few gravel throughout		Hardpan at 24" from bottom		
		24-40	wKsbk-massive R-SCL/CL	fr SSP SZP	28" saturated zone				
2A	L 2%	0-11	gr-sbk brwsd	fr					PS .3
		11-25	SSAB RC	fr-fri SSP SZP					
		25-40	MSBk RCL	fr SSP SZP					
			few mit gravel rock						
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 2/18/97
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Lot 27A (easement) Harbour 4 PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Sl-Ltly Cc 2-4%	0-13	sl/l brn	cl fr sss sp sep	26"+				LPP .125-.15
		13-26	sl/l RC	fi sp sep					
		26-48	sl/l RCL	fi sp sep					
			some gravel, rock 26-30"						
			free H2O pooling in hole between 26-30" some reduced colors (not less than 2)						
2	L 4-6%	0-6	gr brn sl/l	fr					PS .34
		6-18	sl/l brn R	vfr/l CL fr sp sep					
		18-48	sl/l R CL	fr sp-ss sp sep					
3	L ~4%	0-7	brn sl/CL		perched H2O ~24"+				LPP .125-.15
		7-20	sl/l brn RC	fi sp sep					
		20-48	sl/l RCL	fi-fr sp ss sep					
		free H2O coming in hole 24"+ some reduced colors (not less than 2)							
4	L (toe) 4-6%	0-7	gr brn sl/l	fr					
		7-24"	sl/l RC	fi sp sep					
		24-48	sl/l RCL	fi-fr sp ss sp	45"+				
		free H2O ~45"+							

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___