VISION OF ENVIRONMENTAL HEALTH:
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8-02-01
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 556 phs 8 The Pt PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ Do not backfill w/ compacted material
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

Pit ② Now lot 855 Rev. 0-16 compacted silt VFi ⑪ 16-32 SaSb brn/red frssSp 32-49 wkSaSb rd yl cl common mdsp fssp +3716°

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
Pit ①	0-7	gr wkSaSb brn sl/cl	frssSp					.3, .25
	7-30	SaSb RC	fi sp few saprolite rocks					
	30-48	m-wkSaSb yr cl	fi-frssSp few mdsp					
M-5	0-7	wkSaSb brn sl	frssSp					.125-.3
	7-36	MB RC	few fi-frSp					
	36-48	wkSaSb rd yl cl	mdsp frssSp					
Pit ② Now lot 855 Revised	0-8	wkSaSb brn sl	frssSp					.3
	8-22	SaSb RC	fi sp SESp					
	22-45	m-wkSaSb/MB yr cl	common mdsp frssSp					
	45-54	massive rd yl SaSp	frssSp					
Pit ③	0-7	gr brn sl	frssSp					.2
	7-24	MB RC	fi sp					
	24-51	MB RC	few common fine roots few mdsp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____