'SION OF ENVIRONMENTAL HEALTH:
SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

WNER: CRT APPLICANT: _____
DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 7-23-01
OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
CATION OF SITE: lot B17 ph 8 The Pt PROPERTY RECORDED: _____
ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

| .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|
| (1) | 0-8 | Org sandy loam sol | | | | | | |
| | 8-34 | m fsAB RC | fr sp | | | | | .3 |
| | 34-53 | m fsAB yrel | fr ss sp | fe mn sap | | | 36"+/- bdr | |
| | | | | | | | | |
| | | | | | | | | |
| M-14 | 0-40 | sAb RC | fr sp | | | | | |
| | 40-52 | sAb RCl | fr ss sp | | | | | .3 |
| | | m fe mn sap | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| ilable Space (.1945) | | |
| tem Type(s) | | |
| TAR | | |

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

DRIVE
817
8,464 sq.ft.
BASEMENT
CRAWL
818
8,599 sq.ft.
CRAWL
DRIVE
DRIVE
30' Ls Ezmt
Pavement
40'
49'
87'
111'
276'
230'
90'
25'
70'
78'
740
760
785