VISION OF ENVIRONMENTAL HEALTH
I-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CPL APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-23-01
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 731 phe 7 The Pt PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
	0-10	fsgr bwsl-plwsl sd fr						.34
m 36 TC	10-20	wkgrsb rcl	lcsmsthpo fi sssp					>32"
	20-32	wkgrsb rycl	few-common mi sssp					
	32-44	massive vfsl LSMP	fi sssp					
	0-5	wkgrsb bwsl	fr					
(3)	5-22	SAB/AB plwsl	fr SP common yb few mottles					.25 - .34
	22-51	wk fsbk yp cl/sc	fr ss sp					
#17 TC2	0-18	massive compactable w/ bwsl						
	18-39	brittly cl/sc	common mi sssp					.25
	0-9	gr plwsl sd	fr ss sp					
(4)	9-26	wkgrsb yp cl/sc	fr SP few yb few mottles					.25
	26-44	wkgrsb mysl	fr ss sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ailable Space (.1945)		
tem Type(s)		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____