Property ID# _____

County Iredell

Owner/client Dobbins

Proposed facility 5 Home Design flow 600

Site location 193 Alb Brown Property size >1AC

Soil described by TCJ Others present _____

Antecedent moisture dry Weather hot

Water supply: ( ) public (✓) community ( ) on-site well ( ) spring ( ) other Evaluation method: (✓) auger boring ( ) pit ( ) cut

Type of wastewater: (✓) sewage ( ) industrial process ( ) mixed

SOIL/SITE EVALUATION WORKSHEET

Sheet 1

Date evaluated 6/26/12

Site LTAR Int. 0.3 rep. 0.3

Site classification PS

PROFILE #	LANDSCAPE/SLOPE	DEPTH INCHES	HORIZON	COLOR	MUNSELL	TEXTURE	STRUCTURE	CONSISTENCY MOIST	CONSISTENCY WET	MOTTLES	INCLUSIONS	INCLUSIONS	BOUNDARY	COMMENTS
1	C 5	0-4	A1K	red br		scl, sl	gr	fri	NSNP		cmots			
		4-46	B	red		hcl	mm SBK	fri	SS sp-sp	n/a	fwl Fm			
												0.3		
2	C 5	0-3	A1K	red br		scl	gr	fri	NSNP		cgrn mots			
		3-42	B	red		hcl	mm SBK	fri	ss sp to s/p					
		42-46	B3	red		l cl	wk SBK	fri			f wl Fm			
												0.3		
3	C 5	0-5	A1R	red br		scl, l	gr	fri	NSNP		mgt pebbles			
		5-42	B	red		hcl	mm SBK	fri	ss sp to s/p					
		42-46	B3	red		cl	wk SBK	fri	s/p		cf mica flakes			
												0.3		
A	C 5	0-2	A	dk br		sl	gr	fri	NSNP		cmots			
		2-5	E	red br		scl	gr	"	"					
		5-49	B	red		cl	wk SBK	"	ss sp to s/p					
												0.3		
											Approved ICHD 7-2-12 JM			