DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ of ____
PROPERTY ID #: ____
COUNTY: ____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: CRT APPLICANT: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 2-12-97
PROPOSED FACILITY: ____ PROPOSED DESIGN FLOW (.1949): ____ PROPERTY SIZE: ____
LOCATION OF SITE: Lot 15A Harbour 4 PROPERTY RECORDED: ____
WATER SUPPLY: ☐ Private ☐ Public ☑ Well ☐ Spring ☐ Other ____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	1943 SOIL DEPTH	1956 SAPRO CLASS	1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Sampled L.P. slight slope 2-4% 15' from crest	0-3	gr brn scl	fr	36"+				PS .3 @ ≤ 36"
		3-36	SBK rc	fr SPSCP					
		36-48	m-vfSBK rcl	fr SPSCP					
			reduced color	wetness (gy brn)					
			BW approaching clay 2						
2	L 4-6%	0-7	gr brn scl	fr					PS .3
		7-18	SBK rc	fr SPSCP					
		18-48	m-vfSBK rcl	fr SSSPSCP					
			BW-many mica flakes						
3	L 2% ~25' from crest	0-3	gr brn scl			16"			
		3-30	SBK rc	fr SPSCP					
		30-48	m-vfSBK rcl	fr SSSPSCP					
			water comes in hole from notch and						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ____
SITE CLASSIFICATION (.1948): ____
EVALUATED BY: ____
OTHER(S) PRESENT: ____