DEPT OF ENVIRONMENTAL HEALTH
WASTEWATER SECTION

PROPERTY ID #:
COUNTY:

# SOIL/SITE EVALUATION
## *for* ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT:
ADDRESS: APPLICATION DATE: DATE EVALUATED 2-20-97
PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: SR SEC "J" Harbour Dr PROPERTY RECORDED:
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut NCED Prop 5ft p.t's (5')
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed maybe initial trenches @ 48" Hg

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | OTHER PROFILE FACTORS .1943 SOIL DEPTH | OTHER PROFILE FACTORS .1956 SAPRO CLASS | OTHER PROFILE FACTORS .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | L 4-6% Co dispersal trench bottom | 0-7 | gr brsl | fr | | | | | .3 |
| | | 7-10 | SSab brwR | fr sps exp | few brn mottles | | | | |
| | | 10-25 | SBK brwRCL | fr sps exp many yel brn mottles under blades in hole 10-25" | | | | | |
| | | 25-48 | M-wk SAB RCL | fr ss sps exp | | | | | |
| 2 | L 4-6% | 0-5 | gr brsl/sgl | fr | | | | | .35 .25 |
| | | 5-26 | SSab brwR/ yel brn | fr sps exp | | | | | |
| | | 26-48 | M-wk SAB RCL | fr ss sps exp | | | | | |
| | | few yel brn mottles @ 24-30" | | | | | | | |
| | | Some perch H2O seeping in hole from above | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Usable Space (.1945) | | |
| System Type(s) | | |
| | | |

OTHER FACTORS (.1946):
SITE CLASSIFICATION (.1948):
EVALUATED BY:
OTHER(S) PRESENT: