DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET ____ OF ____
PROPERTY I.D.#: _____
PROPERTY RECORDED: _____
COUNTY: _____

# SOIL/SITE EVALUATION
## FOR
## ON-SITE WASTEWATER SYSTEM

APPLICANT: CKT OWNER: AGENT: PHONE: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8/24/95
_____ PROPOSED FACILITY: _____
_____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 14 Highcrest
WATER SUPPLY: On-Site Well ____ Comm. Well ____ Public ____ Other _____ EVAL. METHOD: Auger Boring ✓ Pit ____ Cut ____

| PROFILE # | .1940 LANDSCP POS. (%) | HORIZON DEPTH (IN.) | .1941 STRUCTURE/TEXTURE | .1941 MINERALOGY/ CONSISTENCE | .1942 WETNESS COND. | .1944 RESTRICT HORIZONS | .1948 CLASS OF HORIZ | 1943/ 1956 SAPRLT CLASS. | HORIZON LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | LS 10% | 0-11 | | | | | | | .3 |
| | | 11-28 | | | | | | | |
| | | 28-37" | | | | | | | |
| | | 37-49 | | | | | | | |
| | | | | | | | | | |
| 2 | | 0-16 | | | | | | | .3 |
| | | 16-36 | | | | | | | |
| | | 36-42 | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 3 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 5 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

AVAILABLE SPACE (.1945) ____ SITE CLASSIFICATION (.1948): Prm/1956 SITE LONG-TERM ACCEPTANCE RATE: .3
EVALUATED BY: DH OTHER(S) PRESENT: D. Venegas
COMMENTS: pumped TNF w/ WPPBRS repair - cleanout/fill in "Lean-"