DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH


SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Toney Jacobs, CPSS OWNER: ✓ AGENT: ___ PHONE: ____
ADDRESS: Crescent Resources Inc C APPLICATION DATE: ____ DATE EVALUATED: 7-18-94
PO Box 1003 PROPOSED FACILITY: SFR 360 gpd
Charlotte NC 28201 PROPERTY SIZE: ____
LOCATION OF SITE: The Harbour Lot 47 phase I map D
WATER SUPPLY: On-Site Well ___ Comm. Well ✓ Public ___ Other ____ EVAL. METHOD: Auger Boring ___ Pit ✓ Cut ___

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS	HORIZON LTAR
2		0-6	fsl						
		6-12	fsc						
		12-20	s vwk sbk → massive						
		20-?	saprolite-clay	meti → massive ~24"		by 24"	U	U	
		Pit Terminates in Saprolite, standing water from ~24" from ground surface, reduced organics and mud about 24" deep to solid bottom							
2		boring in bottom of pit brought out moist saprolite							
		Sediment basin (1) and pit 3 show identical profiles							
		pit # 3 also standing in water.							
3									
4									
5									

AVAILABLE SPACE (.1945): — SITE CLASSIFICATION (.1948): U SITE LONG-TERM ACCEPTANCE RATE: NA
EVALUATED BY: AL OTHER(S) PRESENT: NONE
COMMENTS: off site INITIAL + REPAIR


3
OLD RD ECD
2
1
SEDIMENT BASIN
CUT OUT
CREEK

DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET____OF_____
PROPERTY I.D.#:_____
PROPERTY RECORDED:_____
COUNTY:_____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: CBT OWNER:__AGENT:__ PHONE:_____
ADDRESS:_____APPLICATION DATE:_____DATE EVALUATED: 12/10/96
_____PROPOSED FACILITY:_____
_____PROPERTY SIZE:_____
LOCATION OF SITE: 47A The Fenton
WATER SUPPLY: On-Site Well____Comm. Well__✓__Public___Other_____EVAL. METHOD: Auger Boring__✓__Pit___Cut____

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1		0-11	gr-SL	1:1/vfr					.4
		11-42	SBK FCL	1:1/fr-fi					
2									
3									
4									
5									

AVAILABLE SPACE (.1945)_____SITE CLASSIFICATION (.1948):_____SITE LONG-TERM ACCEPTANCE RATE: .4
EVALUATED BY: DRH, JCM OTHER(S) PRESENT: T. Jacobs
COMMENTS:_____