DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: _____
LOCATION OF SITE: Odd site for lot 31 PROPERTY SIZE: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-25	RBSCL wksm	fri sssp	10YR 5/6 common 10YR 6/2 chroma				PS .25 <51"
		25-51	RC mksm	fri 5, P					
		51-54	RC mAm	fi 3, P					
2		0-34	RC AnM/SCM	fri 5 P	3 chroma 10YR 6/2 chroma 45"				PS .25 <45"
		34-48	RSCL WSAM	fri sssP					
3		0-26	RBSCL WSAM	fr sssP	10YR 5/6 common 10YR 6/2 chroma				PS .25 <44"
		26-44	YR SC/SCL WSAM	fri sssP					
		44-50	" "	" "					
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

1" = 50'

N21°10'16"E 196.09'

N68°49'44"W 78.89'

S65°22'30"W 62.50'

S4°01'21"W 106.50'

S50°41'08"E 177.81'

1231A
23,167 sq. ft.
0.532 acres

L69

L68

C70

20' SSLE

C69

N67°28'46"W 237.18'